




Infrared thermal imaging detected the hot leaking glycol which is visible in the photos and thermograms. The origin of the leak was detected at the hottest spot. The use of infrared saved the repair contractor approximately 2.5 hours of labor and needless destructive testing.

Peter W. Bennett
 Certified Thermographer No. 7406
www.AFullHouseInspection.com
 Peter@AFullHouseInspectionCo.com
 732-758-9887



A local veterinarians office has a glycol snow melt system in their sidewalk which was not performing. Infrared imaging detected the cold areas instantly, as indicated by the arrows in the image. Needless, destructive testing was avoided as the pump for the system was defective.